



OFFICE OF THE PRINCIPAL
ADARSHA VIDYALAYA, ROWTA

P.O. KAJIAMATI, DIST: UDALGURI, ASSAM-784509

UDISE CODE: 18260313803

Email Address: avrowta@gmail.com CONTACT NO: 8402961963

Website: <https://adarshavidyalayarowta.com>

Date: 03/05/2024

From:
Julfikar Rahman
Principal cum Member Secretary
Adarsha Vidyalaya, Rowta

Undertaking of Fire Safety

In favour of the Chairman , CBSE , Shiksha Kendra – 2 Community Centre, Preet Vihar , New Delhi – 110092.

I, Mr. Julfikar Rahman , Principal , Adarsha Vidyalaya , Rowta, Kajiamati, Udalguri, Assam undertake the Fire Safety Certificate will be uploaded as soon as it is issued by the competent authority as it has been applied vide application Ref. No: FNESBNOCl/2024/00517 dated 12/03/2024.

Enclo:

1. Relevant Documents.

Julfikar
03/05/2024

Principal
Adarsha Vidyalaya, Rowta

Principal
Adarsha Vidyalaya, Rowta
Date:





Application Acknowledgment

Acknowledgement No: FNESBNOCI/2024/00517

Date: 12/03/2024

Dear JULFIKAR RAHMAN ,

Your application for **Fire NOC for one storey/multistoried/high rise building under Assam Fire Service Rule 1989 Form No I** service has been successfully submitted to Udaguri FnESS Office and Application Ref. No: FNESBNOCI/2024/00517 , Please use this Acknowledgement number for tracking the application and for any future communication related to this application.

***This is a computer generated receipt and therefore needs no physical signature.**

Thank You.



INSPECTION REPORT/ CHECKLIST FOR ISSUANCE OF FIRE SAFETY N.O.C.

UDL/F&ESS/ 44 / 168 /24

DTD. 22/03/24 .

To

The Director,
Fire & Emergency Services,
Assam, Guwahati-1

Through F.P.O (I), Fire & Emergency Services, Assam

SUB:- **Inspection Report**

Ref:- As per online compliance report received on dtd 17/03/2024

Sir,

With reference to the above I have the honour to submit the fire safety audit/inspection of the educational building namely 'Adarsha Vidyalaya Rowta' at Kajiamati conducted on 21/03/2024 on receipt of the online compliance report for N.O.C. from the authorized signatory.

The detailed report in respect of the Educational building is as follows:-


1	Name of Building/ Establishment (with Email -ID of owner/ proprietor)	Adarsha Vidyalaya Rowta avrowta@gmaiil.com		
2	Type of building/ establishment	Educational Building		
3	Height of the building as per approved section plan	6 mtr		
4	Date of application	17/03/2024		
5	Date of inspection	21/03/2024		
6	Land Particulars	Dag no. 121/P	Patta no. Nil	Mouza- Barsilajhar
7	Floor area along with its utilization (as per N.O.C. for construction permission from GMC/GMDA/Municipal Board/ Town Committee/ Gaon Panchayat and approved drawing)	Floor	Area	Utilization
		Ground floor	1522.88 sq mtr	As Classroom purpose
		1 st floor	1522.88 sq mtr	As Classroom purpose
8	Details of surroundings	North: APDCL East: Field	South: Kalicharan Gurudev Hr. School West: Kajiamati H.S. School	
9	Details of Setback	North: 4 mtr East: 4 mtr	South: 4 mtr West: 4 mtr	
10	Provision of parking	Open		
11	Details of fire safety measures	System	Remark	
	(1) Hose reel hose		Nil	
	(2) Down comer system		Nil	
	(3) Wet riser system		Nil	
	(4) Yard Hydrant System		Nil	
	(5) Manually operated electric fire alarm system		1 no. MOLFA points provided and found functional	
	(6) Automatic smoke/heat detection system		Nil	
	(7) Automatic sprinkler system		Nil	
	(8) Fire extinguisher		4 nos provided and found functional	
	(9) P.A. System		Provided and found functional	
	(10) Others		Nil	
12	Fire fighting plan/ Sketch showing the location of fire safety measures installed	Enclosed		

13	Detail status of Fire Extinguishers (IS:15683:2006)	Type	Quantity	Brand	date of manufacturer	date of refill	date of expiry
		A.B.C.	4	Andex	2023	20/10/2023	19/10/2023
14	Details of static water reservoir (Underground/Over ground)	Type: Nil	capacity: Nil				
15	Details of Terrace water tank	Type: Nil	capacity: Nil				
16	Details of Fire Pump	Type	Brand/ Make	Capacity			
		Main Pump	Nil	Nil			
		Electric Pump	Nil	Nil			
		Jockey Pump	Nil	Nil			
		Terrace Pump	Nil	Nil			
17	If Gas Bank is provided then its protection	Nil					
18	No. of Lift/Escalators and details (If provided then the copy of valid Lift Certificate issued by the Chief Inspectors of Lift & Escalators Assam State Guwahati should be submitted)	Nil					
19	Whether lift/fire pumps are connected to DG Set	Nil					
20	No. of staircase & details of handrails	2 nos with handrails					
21	Type of electrification	Concealed & Conduit					
22	Maintenance of housekeeping	Satisfactory					
23	Staff/ security personnel were trained to operate the fire fighting system and familiarization with emergency contact numbers	Trained and can operate					
24	Details of Fire fighting team	Submitted by the Authority and Enclosed.					
25	Display of emergency numbers	Displayed					
26	Display of Emergency Entry/ Exit/ Escape Route Signage	Displayed					
27	Layout of evacuation plan for Schools, Hospitals, Shopping Malls, (Copy Should be submitted)	Displayed					
28	Details of qualified Fire Officer (in case of large educational complexes, business building with height 30m and above, institutional buildings of 15m and above height, starred hotels and D6 occupancies). NBC Pt. IV-2016, Clause:4.10	Nil					
29	Any other information:	✓ Approved building drawing, land related document, Govt notification letter, Fire fighting team and photograph of fire fighting installation is enclosed herewith					

Submitted for favour of your kind perusal and necessary action.

Yours faithfully

Signature:



21/03/24

Full Name of Inspecting Officer: Mrinal Das

Designation: Response Team Commander

Name of F&ES Station: Udaguri

Date: 21/03/24

Response Team Commander

Udaguri Fire & Emergency

Services Station

Udaguri (BTR) Assam